


APEX Engineering • Engineers@TheStructurals.com

482 West Hamilton Avenue 339 • Campbell • CA • 95008

Telephone: 408.378.2068 • Facsimile: 408.378.4602



Tuesday, June 10, 2003

Blake Construction
5874 Red Oak Drive
Saratoga CA 95070

Fax: 408.999.9999

Jobsite: Jacobs Residence
 Monte Sereno, CA
 APEX Job Number **1999-99**
 Re: Framing Review
 Re: Review Summary

Dear Terry,

On Tuesday, June 10, 2003, I visited the aforementioned site at your request to provide field review for the framing of the aforementioned custom home for general conformance with city-approved construction documents pursuant the Building Officials Requirements. During my field walk I reviewed the framing and found it to be in general conformance with the permitted design documents. This review is a nondestructive, qualitative and not quantitative. Engineer does not guarantee construction or placement of items that were not visible or covered at the time of review. The exterior walls were covered at the time of my review.

Other site activities/office reviews:

5.15.2001 Letter to Building Official, re: OK to upgrade FNDN thickness
9.13.2001 Roof Truss Review, re: Layout and Calculations
9.28.2001 Holdown and AnchorBolt Epoxy Review
2.15.2002 Shop Drawing Review, re: Steel Balcony
7.02.2002 Final Framing Review.

All Above Reviews Passed.

Please call our office @ 408.378.2068 if there are any further questions and/or comments.

Sincerely,

Engineer, PE